

Section 36

SUBMIT TO THE DIRECTOR

District Office, JUN 15 1965

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Office

Case No. 20-10-0003-7116

20-10-0003-7116

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANNING	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACID TEST	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PUMP OR ALTER CASING	SUBSEQUENT WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL		

INDICATE ABOVE BY CHECK MARKS NATURE OF WORK, METHOD, OR OTHER DATA

Average Elevation 23-31

Well No. 2 is located 1390 ft. from line and 1400 ft. from line of sec. 36

1/4 Sec. 36
(1/4 Sec. and Sec. No.)Twp.
(Twp.)R. 10E
(Range)T. 36N
(Tertiary)Unincorporated
(Place)San Juan
(County or Political Entity)New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 5121 ft.

DETAILS OF WORK

(Show intervals of well expected depths to objective sands; show sizes, weights, and lengths of proposed strings; indicate mudlogging intervals; and all other important proposed work)

Set bridge plug on wireline at 7080'. Run tubing and packer to 6927'. Ripped up
 wire. Tested bridge plug to 3000 psi, O.K. Perforated selectively interval
 6948-6979 with 11 shots. Added perforations 6948-6979 with 1000 gallons.
 Finished and flowed 264 BW and 6 BW in 3 days. Shut well in. On 4-19-64,
 removed tree, installed 100% puller and tubing. Set cement retainer
 at 6977'. Perforated perforations 6948-6979 with 11 sq. cement. WOC 4-20-64.
 Drilled out cement 6920-7020'. Tested aquifer to 2000 psi, O.K. Run 2-3/8"
 tubing and packer. Set packer at 6964'. Removed 100%, ripped up tree.
 Perforated 6948-6979 with 3 shots. Added perforations with 500 gallons.
 Recovered 85 barrels oil & water, no oil in 3 days. Shut well in and released
 drilling unit 4-27-64.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Company of Texas, a Division of California Oil Company


Address Ingot 16

Houston, Texas

By J. H. Carter

Title District Engineer

ILLEGIBLE



TECHNICAL