UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

	5.	Lease Number
1. Tune of Mell	6	14-20-600-3531
1. Type of Well	6.	If Indian, All. or
Oil		Tribe Name
	100	Navajo
Now of Oreston	7.	Unit Agreement Name
2. Name of Operator		Many Rocks Gallup
BK Petroleum, Inc	n (3)	144 14 14 14 14 14 14 14 14 14 14 14 14
3 Address & Phone No. of Operator On One Operator	8.	Well Name & Number
3. Address & Phone No. of Operator P. O. Box 826, Farmington, NM 87499 (505) 326-3139	$D \approx 10^{\circ}$	Many Rocks #21
P. O. Box 826, Farmington, NM 87499 (505) 326-3139 Con 300	v 🔊 9.	API Well No.
		30-045-12182
Location of Well, Footage, Sec., T, R, M	10.	Field and Pool
		Many Rocks Gallup
1673' FNL and 1789' FEL, Sec. 17, T-31-N, R-16-W,		
	11.	County & State
		San Juan County, NM
40.01501/450505555		
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPOR	RT, OTHER DA	ATA
Type of Submission Type of Action		
Notice of Intent Abandonment Change of Planter		
Recompletion New Constru		
X Subsequent Report Plugging Back Non-Routine	Fracturing	
Casing Repair Water Shut	off	
Final Abandonment Altering Casing Conversion to	to Injection	
Other -		
13. Describe Proposed or Completed Operations		
BK Petroleum plugged and abandoned this well on February 24, 2	2000 per the t	following:
2-22-00 MO, RU. Line pit and layout relief line to pit. Open up well and blow do		
release packer. NU BOP, test. TOH with 44 joints 2-3/8" tubing with M	Nodel "A" packe	er, total 1392'. Set
4-1/2" Downhole CR at 1435'. PT tubing to 500#, OK. PT casing to 50	00# for 15 min,	OK. Plug #1 with
retainer at 1435, spot 21 sxs Class B cement inside casing above CR t	to isolate Gallu	o perforations,
TOC at 1158'. TOH and LD tubing. Perforate 3 bi-wire squeeze holes	at 235'. Estab	lish circulation out
bradenhead. Plug #2 with 81 sxs Class B cement pumped down the 4-	-1/2" casing fro	m 235' to surface,
circulate 1 bbl good cement out bradenhead valve. Shut in well and W	OC.	
2-23-0/ Safety Meeting. Open up well and ND BOP. Dig out wellhead and cut o	off; found ceme	nt in 4-1/2" casing
down 10' and 8-5/8" casing down 8'. Mix 16 sxs Class B cement to fill th		
then install P&A marker. Finish RD and move off location.		
Mike Wade, BLM representative was on location.		
14. I hereby certify that the foregoing is true and correct.		
Signed FO MOUNT Title President		Date 2/25/00
Brad Walls	-W	
This space for Federal or State Office use)	· · · · · · · · · · · · · · · · · · ·	The second secon
APPROVED BY Title		Date FOR RECOR
CONDITION OF APPROVAL, if any:		
•		IAM 1 + 2000

Service Service Service