Form 9-331 b (April 1952)						
		[

Ute 2-29#7

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

indian Agency	.Uto.	_iounti	Ľ
Allottee			
Na 71	20.	(n)1 or	

Sec. 29

SUNDRY	NOTICES	AND	REPORTS	ON	W	El	LL	S				
JU11211-					M	E	P	5	N	W	ß	M

NOTICE OF INTENTION TO REDRILL OR REPAIR WELL NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ALTERING CASINGUE 5 1960 SUBSEQUENT REPORT OF REDRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDON SUBSEQUENT SUBSEQUENT REPORT OF ABANDON SUBSEQUENT SUBSEQ
	II I I I I I I I I I I I I I I I I I I

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

				Aug. 3., 19.60
Ute Mtn. Tribal 2-29 Well No 7 is loca	ted 330 ft.	from $\{S\}$ line a	and 1980 ft. from W	line of sec. 29
SE SE SE 29 (4 Sec. and Sec. No.)	31N (Twp.)	11/17	NAPM	
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
Verde Callup	San Jus	D	Now Lex	ico
(Field)	(Co	unty or Subdivision)	(State o	r Territory)

The elevation of the derrick floor above sea level is 183 ... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The open hole was re-fraced with 70,000 gal. crade and 35,000 lbs. sand with 2 stages mothballs (600lbs.) at 48 BPM at 1500 PSI. The sand was cleaned out to TD and the well is presently producing load oil.

AUG 1 0 1960 OIL CON. COM. DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard 011 Co. of Texas	
Address Box 1581	
Farmington, New Mexico	By Chifiends
	Title Field Personal

