


(SUBMIT IN TRIPLICATE)

Indian Agency Ute Mtn. Tribal

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 11-20-60-122



Sec. 29

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF <u>JUN 6 1960</u>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING <u>U. S. GEOLOGICAL SURVEY</u>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR <u>DURANGO, COLO.</u>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY <u>1</u>
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 3, 19 60

Ute Mtn. Tribal 2-29

Well No. 11 is located 2310 ft. from N line and 660 ft. from W line of sec. 29

SW 1/4 of NW 1/4, Sec. 29 31N 11W R4P1
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)


Verde Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5557 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded on 5-27-60. Set 8 5/8" casing at 111.65' and cemented to surface with 100 sacks neat cement. Pressure tested casing OK with 1000 PSI after 24 hours waiting on cement. Drilled 6 3/4" hole below 8 5/8" casing, now drilling at 3000'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil Company of Texas

Address Box 1591

Farmington, New Mexico

By

Title Field Foreman

