

Form 9-331b
(April 1952)

(SUBMIT IN TRIPLICATE)

Indian Agency _____

Ute Mountain Tribal

Allottee _____

Lease No. 14-20-04-84

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 2, 1960

Well No. Trials is located 1450 ft. from N line and 660 ft. from E line of sec. 30

N 30 Sec. 30 (1/4 Sec. and Sec. No.)
Verde Gallup (Field)
31N (Twp.)
14W (Range)
San Juan (County or Subdivision)
14W (Meridian)
New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 9523 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 2:30 a.m. 2-2-60. Drilling 11" hole to 137'.
Ran 4 lbs. 121.30' of 1-1/8" O.D. 32 J-55 S-2, 3760, CFI ends. eng. set
136' w/125 ex. regular cement, 2% calcium chloride. Plug down 1:20 p.m. 2-2-60.
Cement circulated to surface. W.O.C. 24 hours. Test plug w/300 psi for 30 min. OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Three States Natural Gas Company

Address Box 67
Harrington, New Mexico

By Original Signed By John Carruthers

Title Assistant District Supt.