

RECEIVED

(SUBMIT IN TRIPLICATE)

		X

AUG 23 1960

UNITED STATES

CONTRACT 14-20-60-124

DEPARTMENT OF THE INTERIOR
U. S. GEOLOGICAL SURVEY
DURANGO, COLO. GEOLOGICAL SURVEY

Indian Agency _____

Allottee _____

Lease No. Co. 234467

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Begin Drilling Operations

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

UTE INDIAN "B"

AUGUST 8, 1960

Well No. 3 is located 1980 ft. from ~~N~~ S line and 660 ft. from ~~E~~ W line of sec. 25

NE/4 of SE/4

31-N

15-W

(4 Sec. and Sec. No.)
VERDE GALLUP

(Twp.)
SAN JUAN

(Meridian)
NEW MEXICO

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is LATER ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12-1/4" hole at 3:00 P.M. 8-5-60. Finished hole at 10:15 P.M. Ran 130' 8-5/8" J-55 csg, set at 139'. Cement with 150 sacks 2% Cal Chl, POB 2:40 A.M. 8-6-60. Cement circulated. Tested csg with 1000# for 30 min-no drop in pressure. Drilled cement plug at 5:30 A.M. 8-7-60. Drilling.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company HUMBLE OIL & REFINING CO.


Address BOX 2347,

HOBBS, NEW MEXICO

By ORIGINAL
SIGNED: ARVIN D. EADY

Title AGENT

1000



1000

1000