

		X	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo-Ute

Tribal Coun.

Allottee

Lease No. **14-20-604-1951**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED

1980

U. S. GEOLOGICAL SURVEY

DENVER, CO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 29 19 60

Horse shoe Uta

Well No. 33 is located 660 ft. from S line and 2055 ft. from E line of sec. 27

SW SE/4 Section 27

31N

16W

NMPM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Horseshoe Gallup

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 5457 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

January 27, 1960 Total Depth 1465'.

Ran 47 joints 5-1/2", 15.50#, J-55 Casing (1457') set at 1463' with 100 sacks regular cement, 4% gel., 1/4# Floccs per sack. Held 1000#/30 Minutes.

Top of cement by temperature survey at 775'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Products Company

Address **Post Office Box 1565**

Farmington, New Mexico

ORIGINAL SIGNED BY: JOSEPH E. KREGER
By _____

Title **Petroleum Engineer**



RECEIVED FEB 1963