

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ - Injection
well well
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of
Atlantic Richfield Company
3. ADDRESS OF OPERATOR 707-17th Street,
P.O. Box 5540, Denver, CO 80217
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17
below.) Unit "p"
AT SURFACE: 610' FSL & 640' FEL, Sec. 27
AT TOP PROD. INTERVAL: Appx. same
AT TOTAL DEPTH: Appx. same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE
14-20-604-1951
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Ute Mountain
7. UNIT AGREEMENT NAME
Horseshoe Gallup Unit
8. FARM OR LEASE NAME
Horseshoe Gallup Unit
9. WELL NO.
173
10. FIELD OR WILDCAT NAME
Horseshoe Gallup Unit
11. SEC., T., R., M., OR BLK. AND SURVEY OR
AREA
Sec. 27-31N-16W
12. COUNTY OR PARISH: 13. STATE
San Juan New Mexico
14. API NO.
None Assigned
15. ELEVATIONS (SHOW DF, KDS. AND WD)
5683' GR

RECEIVED

Bureau of Land Management

(NOTE: Report results of multiple completion or zone
change on Form 9-330.)

DEC 27 1983

Durango, Colorado

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ARCO has plugged and abandoned the subject well in accordance with the Sundry Notice dated December 30, 1982, and approved by the BLM-MMS on January 13, 1983. Injection interval 1604' - 1633', Gallup fm. Spotted cement plugs as per the attached plugging operations report.

Completed P & A, 8-1-83.

Final restoration will be commenced as soon as weather permits. An additional subsequent report will be filed when restoration has been completed.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Stephen Rose TITLE Dist.Prod. Supt. DATE November 30, 1983
S. C. Rose

(This space for Federal or State office use)

APPROVED BY L. Mark Hollis TITLE AREA MANAGER DATE MAR 31 1987
CONDITIONS OF APPROVAL IF ANY: