Form 9-831 b (April 1952)

(SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Allottes Bushle Q & R

Allottee **Euroble Q & R**Lease No. 14-20-603-1255

## SUNDRY NOTICES AND REPORTS ON WELLS

	AND REPORTS ON WELLES
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO CHARGE TELESCOPE NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO DESPITE OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO PULL OR ALTER CASING.	
NOTICE OF INTENTION TO ARANDON WELL	
(INDICATE ABOVE BY CHECK MARI	rk nature of report, notice, or other data)
	Xereb 26, 1965 , 19
Well No. 1 is located 1744 ft.	from N line and 990 ft. from line of sec. 17.  (Meridian)
marana Ann Juan	(State or Territory) - 1 B7 F
(Field) (Coun	ID) E G E I V E I
The elevation of the derrick floor above sea	level i <b>3077</b> ft.
DET	TAILS OF WORK MAR 27 1963
(State names of and expected depths to objective sands; show	w sizes, weights, and lengths of proposed casings; indicate mudding jobs, comentall other important proposed work)  U. S. GEOLOGICAL SURVE
ing points, and a	U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXIC
Well completed as water well	by The Navajo Tribe.
	ALEN 110 SHEEF TORUSE TO ALL THE PROPERTY OF T
Drilled 52 feet below limer	to a total depth of 1282 feet KLULI
Well flowed water at well her	CON
	OIL DIST. 3
I understand that this plan of work must receive approv	wal in writing by the Geological Survey before operations may be commenced.
•	
Company Leora O. Shaw	
Company Leora O. Shaw	- Solx Park
Address 1007 Vest Apache Street	- Selfin
Company Leora O. Shaw	By Hallyre