

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078096
Unit Mudge

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 9, 19 61


Well No. 20 is located 1450 ft. from N line and 1550 ft. from E line of sec. 8
NE/4 Sec. 8 31N 11W N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Basin Dakota San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6033 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was originally drilled by Delhi-Taylor Oil Corp. as the Mudge No. 5. El Paso Natural Gas Co. has purchased this well with name changed to the El Paso Natural Gas Co. Mudge No. 20. El Paso Natural Gas Co. will be the operator.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company
Address Box 990
Farmington, New Mexico

By ORIGINAL SIGNED U.J. TILLERSON
Title Petroleum Engineer

7-26-60

F. Loc. 1450/N; 1650/E Elev. 6085 GL Spd. 1-1-68 Comp. 9-1-68 TD 7452 PB _____
Casing S. 1 3/4 @ 100 W 200 Sx. Int. 1 1/2 @ 7447 W 200 Sx. Fr. 1 1/2 @ 5001 W 200 Sx. T. 2 3/4 @ 7051
Csg. Perf. _____ Prod. Stim. _____
7130-72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
7141 BO/D
I.P. 1671 MCF/D After 3 Hrs. SICP 2412 PSI After 7 Days GOR _____ Grav. _____ 1st Del. _____

TOPS		NITD	X	Well Log	TEST DATA							
Kirtland		C-102		Plat	X	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland		C-103	✓✓✓✓	Electric Log	✓							
Pictured Cliffs	2250	C-104		C-110								
Cliff House	4002			C-122	✓							
Menefee	4.1	Ditr		Dfa								
Point Lookout	4472	Datr		Dac								
Mancos		Remarks										
Gallup	6373											
Dakota	7216											
Morrison	7422											
Entrada												
Greenhorn	7620											
		E320										

Basin Dak. SJ 8 T 3IN R 11W 11G Owner Delhi-Taylor Lsa Mudge No. 5