

(SUBMIT IN TRIPLICATE)

Indian Agency Consolidated

UNITED STATES

Ute

DEPARTMENT OF THE INTERIOR

Allottee 14-20-604-83

GEOLOGICAL SURVEY

Lease No. Ute Mountain

	X		
		22	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	X	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	AUG 7 1961
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 3, 1961

Well No. 14 is located 650 ft. from N line and 1690 ft. from W line of sec. 22

NW/4 Sec. 22

31N

14W

NMPM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Verde-Gallup

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

grd. level

The elevation of the ~~surface~~ grd. level above sea level is 5669 ft. 5680' F.S.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drld 7-7/8" hole from 135' (8-5/8" csg. shoe) to 2630' w/mud.
Cemented 81 joints, 2618' of 5 1/2", 14#, J-55, ST30 csg. @ 2630' w/215 sx
+ 85 gal 1 1/2" Flo-cole/sx plus 35 sx neat. Plug down 3 PM,
8/1/61. Ran temperature survey; top cmt - 1225'. Pressure tested
w/1000 psi for 30 min., ok.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Socony Mobil Oil Company, Inc.

Address P. O. Box 3371
Durango, Colorado

By P. M. Barry by RD
P. M. Barry
Title Dist. Prod. Supt.

cc: ESGS (5)
GPY (1)
Dgo (1)