

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R14245. LEASE DESIGNATION AND SERIAL NO.
NM-013686

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Pritchard9. WELL NO.
510. FIELD AND POOL, OR WILDCAT
Basin Dakota11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 34, T-31-N, R-9-W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6007 GR12. COUNTY OR PARISH
San Juan13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL



ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well spudded 3-26-71 with 15" hole and drilled to TD of 191', Ran 6 jts of
10-3/4" 32.75# casing Landed at 191', cemented with 185 sacks, circulated.
Tested BOP and casing to 1000 psi, held O.K.
Drilled out with 9-7/8" hole and drilling as of 3-29-71 at 2280'



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Sr. Production Clerk

DATE

3-30-71

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side