

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator <b>AMOCO PRODUCTION COMPANY</b>	8. Farm or Lease Name <b>Canephe Gas Com "C"</b>
3. Address of Operator <b>501 Airport Drive, Farmington, New Mexico 87401</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>K</b> , <b>1510</b> FEET FROM THE <b>South</b> LINE AND <b>1700</b> FEET FROM THE <b>West</b> LINE, SECTION <b>18</b> TOWNSHIP <b>31-N</b> RANGE <b>10-W</b> NMPM.	10. Field and Pool, or Wildcat <b>Blanco Pictured Cliffs</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>5742' Gr.</b>	12. County <b>San Juan</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Spud &amp; set casing</b>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

A 12-1/4" hole was spudded 2:00 p.m., October 26, 1972, and boulders were encountered while drilling from 15' to 110'. Continued drilling to 242' with the 8-5/8" casing set at 241' with 250 sacks Class "A" cement with 2% CaCl<sub>2</sub>. The cement circulated. The hole was reduced to 7-7/8" at 241'.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by  
SIGNED J. ARNOLD SNELL TITLE Area Engineer DATE October 31, 1972

Original Signed by Emery C. Arnold TITLE SUPERVISOR DIST. #3 DATE NOV 2 1972

CONDITIONS OF APPROVAL, IF ANY: