UNITED STATES DEPARTMENT OF THE INTERIOR

Dec. 1973	Buoget Buteau (10) 42-11121
UNITED STATES	5. LEASE 10 10 10 10 10 10 10 10 10 10 10 10 10
DEPARTMENT OF THE INTERIOR	14-20-604-79
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Ute Mountain Tribe 7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON	WELLS The state of
oo not use this form for proposals to drill or to deepen or plug back servoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
servoir, ose rolling-social of the servoir	Mountain Ute Gas Com "E"
1. oil gas X other	9. WELL NO.
2. NAME OF OPERATOR	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
AMOCO PRODUCTION COMPANY	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Ute Dome Dakota
501 Airport Drive. Farmington, N.M.	87401 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, S.	ee space 17 ARLA SW/4 NE/4 Section iu
helow)	T-31-N, $R-14-W$ 12. COUNTY OR PARISH 13. STATE
AT SURFACE: 1850' FNL x 1790' FEL AT TOP PROD. INTERVAL: Same	San Juan New Mexico
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	14. API NO. 2. 5. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6343' GL 6357' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REF	
TEST WATER SHUT-OFF	
FRACTURE TREAT USE SHOOT OR ACIDIZE USE USE USE USE USE USE USE USE USE US	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING 🔲	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	
(other)	
	(Clearly state all pertinent details, and give pertinent dates,
including estimated date of starting any proposed wo	rk. If well is directionally drilled, give subsurface locations and
including estimated date of starting any proposed we measured and true vertical depths for all markers and	zones pertinent to this work.)
Plugging operations commenced 12/26/	78, squeezed perforations 2920-2936
with 40 sx Class B neat, tripped in	with tubing and filled hole with water
held ok, spotted 70 sx Class B hear	2540', cut off well head and spot
TO SK CIGOO I III	
unit 12/27/78.	ED TO THE IN FIND
JAN2	1979
VOIL CON. €	оом. / DEC+20 1978
DIST.	3
	U. S. CONDITION SURVEY
	PROPERTY OF THE PROPERTY OF TH
Subsurface Safety Valve: Manu, and Type	Set @Ft
18. I hereby certify that the foregoing is true and correct	
Original Stand By	st. Adm. Super. December 28, 1978
2IGHED	
(This space for Federal or State office use)	
TITLE	DATE
APPROVED BY	