



STATE OF NEW MEXICO
ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

September 4, 1990

Mr. Gary Munson
Amoco Production Co.
San Juan Operation Ctr.
200 S. Amoco Crt.
Farmington, NM 87401

RE: Heaton LS #30, O-28-**31N-11W**

Dear Gary:

The regularly scheduled Bradenhead Test on the referenced well indicated a casing leak. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate immediate remedial activity.

Yours truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson
Deputy Oil & Gas Inspector
District III NMOCD

CG:sh

xc: Well File