APPROVED BY \_\_\_\_\_\_\_CONDITIONS OF APPROVAL, IF ANY:

Dec. 1973	Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 078507
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	San Juan 32-9
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1, oil — gas 👽	San Juan 32-9 Unit
well gas X other	9. WELL NO.
2. NAME OF OPERATOR	81
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Undes Fruitland
P. O. Box 990, Farmington, N. M.	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 26, T32N, R10W
below.)	
AT SURFACE: 18001/S, 16001/W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: 1080 AT TOTAL DEPTH:	San Juan New Mexico
	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6961' GL
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statingly including estimated date of starting any proposed work. If well is different and true vertical depths for all markers and zones pertinent.)	irectionally drilled, give subsurface locations and
This location has been cleared of all e	
inspection.	
1113770001771	
Deseeding will be done later.	•
	25.
	e de la companya de
	200 July 200 V
Subsurface Safety Valve Manu. and Type	Set @
18. Thereby certain that the foregoing is true and correct	
Div. Product	ion 8-22-78
SIGNED TITLE Engineer	DATE 0-44-78

(This space for Federal or State office use)

\_\_\_\_\_ TITLE \_\_\_\_\_