## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Bureau of Land Management

Date of Courses Sundry Notices and Reports on Wells 5. Lease Number M00-C-1420-0625 1. Type of Well 6. If Indian, All.or GAS Tribe Name Ute Mountain Tribe <u>JAN1 1 1990</u> 7. Unit Agreement Name 2. Operator OIL CON. D' Meridian Oil Inc. DIST. 🕄 8. Farm or Lease Name 3. Address & Phone No. of Operator Pinon Mesa B PO Box 4289, Farmington, NM 87499 9. Well No. 4. Location of Well 10.Field, Pool, Wildcat 1840'S, 1060'W Basin Dakota 11.Sec. T. R. M. or Blk Sec.25, T-31-N, R-14-W NMPM 14. Permit No. 15. Elevations 12.County 13. State 5616'GR San Juan NM 16. Intent to/Subsequent Report of : Casing Repair 17. Describe proposed or completed operations: 7-21-89 Mol ru. Tih w/2 3/8" tbg set @ 366', est inj rate. Squeezed 60 sx "B" , 1% cacl, 2.25% CFR, 160 sx (70.8 cu.ft.) Circ thru bradenhead, shut it. Test failed. Tih w/2 3/8" tbg set @ 355', est inj rate. Re-squeezed 150 sx 7-23-89 "B" 1% cacl, 10 bbls /sx calseal (195 cu. ft.). Woc. Circ down tbg & tested to 500 psi. 7-26-89 Sting into retainer. Landed well w/193 jts 2 3/8", J-55, EUE, 8rd tbg set @ 6039.59'. Nd bop, Nu upper tree. Rig released. 18. Authorized by Regulatory Affairs NOTE: This format is issued in lieu of US BLM Form 3160-5 (This space for Federal or State office use) APPROVED BY \_ TITLE \_\_\_\_\_ DATE\_ CONDITION OF APPROVAL, IF ANY:

Nmocs