## UNITED STATES

UNITED STATES	5. LEASE /200
DEPARTMENT OF THE INTERIOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	Mountain Ute Sand
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	
1. oil gas other	9. WELL NO. 9776 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
2. NAME OF OPERATOR Energetics, Inc.	10. FIELD OR WILDCAT NAMÉ
3. ADDRESS OF OPERATOR	Verde Gallup
102 Inverness Terrace East, Englewood, CO 801	21. SEC., T., R., M., OR BLK. AND SURVEY OR
<ol> <li>LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)</li> </ol>	AREA
AT SURFACE: 640' FSL & 1650' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	San Juan REW Mexico
AT TOTAL DEPTH: Same	14. API NO. 10 10 10 10 10 10 10 10 10 10 10 10 10
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6035 GL 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	30 3 4 1
FRACTURE TREAT	
SHOOT OR ACIDIZE	O S T S T S T S T S T S T S T S T S T S
REPAIR WELL U	(NOTE: Report results of multiple completion of zend
MULTIPLE COMPLETE	
CHANGE ZONES	
other)	A STATE OF THE CONTRACTOR
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, and give persinent dates.
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	rectionally drilled, give subsurface locations and
measured and true vertical deptits for all markers and zones pertinen	t to this work. It is a second of the second
6-9-80: Rig up mast pole. Perforate at 100' v	with 2 jets: 6-12-80 MIRUPU-
Farmington Well Service. Ran 76 joints 2 3/8"	
Dump 3400# 20-40 mesh sand. Trip in hole with	
Spot 40 sacks class "B" cement plug from 2112-7 hole with water. Cement 5 1/2" & 8 5/8" x 5 1/2"	
"B" cement. Circulate estimate 3 barrels. 6-	
6-24-80 Clean up location. Well plugged and a	
	abandoned. Habita habit
	mid en of record of record of record of the of the
	Hitche hot but in the
	Toby Sanda Sand Sand
Subsurface Safety Valve: Manu. and Type	Set @Ft.
18. I hereby certify that the foregoing is true and correct	
	DATE 8-28-80 F - 1 4 F
Jack D. Look Agent	DATE 8-28-80
(This space for Federal or State office	ce use)
APPROVED BY TITLE	DATE DATE
CONDITIONS OF APPROVAL, IF ANY:	
	CIVED
	See See See See M
*See Instructions on Reverse Si	ide 3EP 2 1980



U. S. GEOLOGICAL SURVEY FURNISO, COLO.