UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 078118 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil gas well other 2. NAME OF OPERATOR Mesa Petroleum Co. 3. ADDRESS OF OPERATOR 1660 Lincoln, Suite 2800, Denver CO 80264 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1690' FNL & 1725' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	8. FARM OR LEASE NAME JOHNS FEDERAL 9. WELL NO. 5 10. FIELD OR WILDCAT NAME BLANCO PICTURED CLIFFS 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 18-T32N-R11W 12. COUNTY OR PARISH 13. STATE SAN JUAN NEW MEXICO
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA EQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: EST WATER SHUT-OFF	14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6683 GL (NOTE: Report results of multiple completion on Form 9–330.)

AT SURFACE: 1690' FNL & 1725' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Spud and test BOP

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ON. COM.

A 12-1/4" hole was spudded @ 5:00 PM March 10, 1981 and drilled to 236' KB. 5 joints of 8-5/8" 24#/foot new K-55 STC casing were set @ 228' and cemented with 250 sxs Class "B" 2% CaCl. Good circulation, circulated 12 bbls of slurry to the surface. The plug was down 0 10:15 PM March 10, 1981. The BOP was tested to 1000 psi for 30 minutes and held OK.

Subsurface Safety Valve: Manu. and Type Set @ ____ Ft. 18. I hereby certify that the for going is true and correct TITLE Div. Drlg. Super. DATE March 12, 1981 (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

See Instructions on Reverse Side

ACCEPTED FOR RECORD

MAR 17 1981