

NO. OF COPIES RECEIVED		
DISTRIBUTION		
AMOUNT FE		
LE		
S.G.S.		
AND OFFICE		
PERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

API #30-045-25031

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-503-9	
7. Unit Agreement Name	
San Juan 32-7 Unit	
8. Farm or Lease Name	
San Juan 32-7 Unit	
9. Well No.	
27A	
10. Field and Pool, or Wildcat	
Blanco MV/So Los Pinos PC	
12. County	
San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐

Name of Operator
Northwest Pipeline Corporation

Address of Operator
P.O. Box 90, Farmington, New Mexico 87401

Location of Well
UNIT LETTER C 900 FEET FROM THE North LINE AND 1790 FEET FROM
THE West LINE, SECTION 36 TOWNSHIP 32N RANGE 7W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
6526' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

9-5/8" Csg depth correction ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

As reported on Report dated 8-18-81 the corrected depth for the 9-5/8" csg should be 204' instead of 202'

As reported on Report dated 11-10-81 the corrected depth for the 2-3/8" tbg should be 5817' instead of 5779' and on the 1-1/2" tbg landed at 3370' instead of 3375'.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Donna J. Brace</u> Donna J. Brace	TITLE <u>Production Clerk</u>	DATE <u>2-11-82</u>
APPROVED BY <u>Original Signed by FRANK T. CHAVEZ</u>	TITLE <u>SUPERVISOR DISTRICT # 3</u>	DATE <u>2-11-82</u>

CONDITIONS OF APPROVAL, IF ANY: