

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other
2. NAME OF OPERATOR
Northwest Pipeline Corporation
3. ADDRESS OF OPERATOR
P.O. Box 90, Farmington, N.M. 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1910 FSL & 1840 FEL
AT TOP PROD. INTERVAL: Same as above
AT TOTAL DEPTH: Same as above
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

5. LEASE
SF 078996
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
San Juan 32-7 Unit Com
8. FARM OR LEASE NAME
San Juan 32-7 Unit Com
9. WELL NO.
#79
10. FINDER OR WILDCAT NAME
Blanco MV/ Undesignated PC
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 7, T31N, R7W
12. COUNTY OR PARISH | 13. STATE
San Juan | N.M.
14. API NO.:
30-045-25207
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6548' GR

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other) _____	

	X				

RECEIVED (NOV)

Jan 1957

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-28-81 to 12-2-81 Blowing well w/ compressor.

12-3-81 & 12-4-81. Dresser Atlas set Baker Model "F" Production Packer @ 3654' KB. Ran 183 jts (5731') of 2-3/8", 4.7#, J-55, CF&I & landed @ 5737' KB. Ran 101 jts (3351') of 1-1/4", 2.33#, J-55 IJ & set @ 3357' KB. Pumped out plugs & gauged well up tbg. Turned over to Production Department. Rig released @ 0600 hrs 12-4-81.

NOW WAITING ON IP TEST.

Subsurface Safety Valve: Manu. and Type

Set @ CON. 1000 Ft
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Donna J. Brace TITLE Production Clerk DATE 12-8-81

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL IF ANY _____

TITLE _____ DATE _____

ACCEPTED FOR RECORD

JAN 18 1992

FARMINGTON DISTRICT

BY Sm

*See Instructions on Reverse Side

NMOCC