

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR  
Northwest Pipeline Corporation

3. ADDRESS OF OPERATOR  
P.O. Box 90, Farmington, N.M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1910 FSL & 1840 FEL  
AT TOP PROD. INTERVAL: Same as above  
AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:  
TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) Production Csg.

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE  
SF 078996

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
San Juan 32-7 Unit Com

8. FARM OR LEASE NAME  
San Juan 32-7 Unit Com

9. WELL NO.  
#79

10. FIELD OR WILDCAT NAME  
Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec 7, T31N, R7W

12. COUNTY OR PARISH | 13. STATE  
San Juan | N.M.

14. API NO.  
30-045-25207

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6548' GR

(NOTE: Report results of multiple completions or zone change on Form 9-330.)



17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

10-26-81 & 10-27-81 Gearhart ran Induction, GR/CDL/SNP across MV. Ran 58 jts (2236.5') of 4-1/2", 10.5#, K-55, ST&C & set liner from 5951' to 3715'. KB. Float Collar @ 5928'. National pumped 30 bbls gel wtr & cmt'ed w/ 230 sx C1 "B" w/ 4% gel & 12-1/2# fine gils/sx. Displaced plug w/ 60 bbls wtr & down @ 2055 hrs 10-26-81. Reversed out 25 bbls cmt. Released rig @ 0200 hrs 10-27-81.

NOW WAITING ON COMPLETION.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Donna J. Brace TITLE Production Clerk DATE 12-8-81  
Donna J. Brace

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL IF ANY

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

ACCEPTED FOR RECORD

DEC 09 1981

\*See Instructions on Reverse Side

NMOCC

FARMINGTON DISTRICT  
BY Smm