REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Dec. 1973	Budget Bureau No. 42-R142			
UNITED STATES	5. LEASE			
DEPARTMENT OF THE INTERIOR \	SF 079353			
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME San Juan 32-8 Unit			
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME San Juan 32-3 Unit			
well Well W other	9. WELL NO. #46			
2. NAME OF OPERATOR	π40			
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME			
3. ADDRESS OF OPERATOR	Blanco MV / So Los Pinos PC			
P.O. Box 90, Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR			
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA			
below.)	Sec 14, T32N, R8W			
AT SURFACE: 1820 FNL & 790 FEL	12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL: Same	San Juan N.M.			
AT TOTAL DEPTH: Same	14. API NO. 30-045-25127 15. ELEVATIONS (SHOW DF, KDB, AND WD) 7007 GR			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE				
REPORT, OR OTHER DATA				

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

MULTIPLE COMPLETE u. S. MOUTGIONE SURVEY CHANGE ZONES FACTOR OLIN, N. W. ABANDON\* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates. including estimated date of starting any proposed work. If well is directionally drilled, give substarface locations and

SUBSEQUENT REPORT OF:

12-18-81 to 12-23-81 Blowinc PC & MV w/ compressor.

measured and true vertical depths for all markers and zones pertinent to this work.)\*

12-24-81 Blue Jet set Model "F" Production Pkr @ 4050'. Ran 197 jts (6141') of 2-3/8", 4.7#, J-55, 8rd EUE & 6 jts (120') of 14.5# Baker Blast jts & landed @ 6273' KB w/ SN @ 6268'. Ran 114 jts (4022) of 1-1/4", 2.33#, J-55, IJ tbg and landed @ 3906' w/ SN @ 3900'. Nippled up and pumped both plugs. Gauged well up tbg strings. Released rig @ 0600 hrs 12-24-81. Well turned over to production Department.

WELL WAITING ON IP TEST.

				HAN 6 1992
Subsurface Safety Valve: Manu. ai	nd Type		Se	et @ <u>JAN</u> Ft
18. I hereby certify that the forego	oing is true and correct			Non Comme
SIGNED VOMMON J	Dine is true and correct  Production	Clerk DATE	Dec 30,	1981
DUIIII V DI d'	(This space for Federal or Stat	te office use)		
APPROVED BY	TITLE	DAT	2GGEPTED	FOR RECORD

JAN 07 1992