

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR  
Northwest Pipeline Corporation

3. ADDRESS OF OPERATOR  
P.O. Box 90, Farmington, N.M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1570 FNL & 930 FWL  
AT TOP PROD. INTERVAL: Same as above  
AT TOTAL DEPTH: Same as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

(other) Spud Operations

5. LEASE  
SF 079353

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
San Juan 32-8 Unit

8. FARM OR LEASE NAME  
San Juan 32-8 Unit

9. WELL NO.  
#40A

10. FIELD OR WILDCAT NAME  
Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec 33, T32N, R8W

12. COUNTY OR PARISH  
San Juan

13. STATE  
New Mexico

14. API NO.  
30-045-25131

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6766' GR

RECEIVED

OCT 20 1981

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or one change of Form 9-330.)

OCT 20 1981  
OIL CON. COM.  
DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

10-10-81 to 10-11-81 MOL & RU. Spudded 12-1/4" surface hole @ 1830 hrs. Ran 5 jts of 9-5/8", 32.3#, H-40, ST&C & set @ 221'. Woodco cmt'ed w/ 130 sx C1 "B" w/ 2% CaCl<sub>2</sub> & 1/4# gel flake/sx. Plug down @ 0100 hrs 10-11-81. Circ out 5 bbls cmt.

10-12-81 to 10-13-81 Drlg ahead to a depth of 4088'.

10-14-81 to 10-15-81 Ran 108 jts (4076') of 7", 20#, K-55, ST&C csg & set @ 4088'. HOWCO cmt'ed w/ 100 sx 65/35 poz w/ 12% gel. Tailed w/ 75 sx C1 "B" w/ 2% CaCl<sub>2</sub>. Plug displaced w/ 160 bbls & down @ 0240 hrs 10-15-81. Wilson ran temp survey & top of cmt @ 2600', PBD @ 4025'.

10-16-81 Drlg ahead to a depth of 6220' w/ gas.

10-17-81 TD'ed hole (6220'). Gearhart ran IES & SNP/CDL/GR logs. Ran 61 (2327') of 4-1/2", 10.5#, K-55, ST&C csg & set from 6209' to 3881' KB. Float Collar @ 6167' KB. HOWCO cmt'ed w/ 230 sx C1 "B" w/ 4% gel & 12-1/2# fine gils/sx. Displaced plug w/ 68 bbls wtr & down @ 2115 hrs 10-17-81. Reversed out 25 bbls cmt. Rig released @ 0200 hrs 10-18-81 NOW WAITING ON COMPLETION

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Donna J. Brace TITLE Production Clerk DATE 10-27-81  
Donna J. Brace

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

AMOC