

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Southland Royalty Company 3. Address of Operator P.O. Drawer 570, Farmington, New Mexico 87499 4. Location of Well UNIT LETTER <u>B</u> <u>790'</u> FEET FROM THE <u>North</u> LINE AND <u>1830'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>3</u> TOWNSHIP <u>31N</u> RANGE <u>12W</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 6168' GL	7. Unit Agreement Name 8. Farm or Lease Name Decker "A" 9. Well No. #2E 10. Field and Pool, or Wildcat 12. County San Juan
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Perforation & Stimulation Report

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-17-83 Tested casing to 3500 psi. Perforated the Dakota at 7143', 7147', 7219', 7229', 7233', 7259', 7265', 7269', 7273', 7277', 7281'. Total of 11 holes. Frac'd with 52,300 gallons of CO₂ and 31,250# 30/50 sand. ATP 1750 psi, AIR 20.5 BPM, ISIP sanded off.

8-19-83 Lande 239 joints (7268') of 2-3/8", 8rd tubing at 7279'.

11-1-83
OIL CONSERVATION DIVISION
SANTA FE, N.M.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Sherry Sherkey TITLE Secretary DATE August 22, 1983

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE AUG 22 1983

CONDITIONS OF APPROVAL, IF ANY: