

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
SOLAR PETROLEUM, INC.

3. ADDRESS OF OPERATOR
999 18th Street, #1300, Denver, CO 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1310' FSL & 2630' FWL

14. PERMIT NO.

15. ELEVATIONS (Show vertical depth of well)
5255' GR

5. LEASE DESIGNATION AND SERIAL NO.
14-20-603-2034

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Navajo Tribe of Indians 'F'

9. WELL NO.
160

10. FIELD AND POOL, OR WILDCAT
Horseshoe Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 4-T31N-R17W

12. COUNTY OR PARISH
San Juan

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	SPUD <input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The above well was SPUDDED @ 1:00am, 8/17/83. U.S.G.S. Was contacted on 8/17/83.
Report as follows:

8/17/83 88' (88') rng sfc csg. SPUDDED @1:00am, 8/17/83. Drld 12 1/4" hole to 88', now rng 8-5/8" csg.

8/18/83 430' (342') drlg. RU & rn 2 jts 24# K-55 Rg3, 8-5/8" csg w/ Howco guide shoe (tallied @ 79.7'). Set @ 82.7'KB w/ 1 centralizer 10' up from shoe. Cmtd w/ 20sx Class 'B' w/ 2% CaCl2 & 1/4#/sx flocc. Good returns to sfc. PD @ 8:00am, 8/17/83.

82.6 cu ft

change well name from Navajo F

James Drilling Company, Farmington, NM, is the contractor

RECEIVED

SEP 1 1983

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED David S. Cushman TITLE Staff Petroleum Engineer DATE 8/18/83

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NMOCC

AUG 31 1983

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA
BY KI