

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well <input type="checkbox"/> gas well <input checked="" type="checkbox"/> other	5. LEASE SF-078097
2. NAME OF OPERATOR BASIN MINERALS, INC.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR c/o Walsh Engr. & Prod. Corp. P.O. Drawer 419 Farmington, N.M. 87499	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 950' FSL, 1005' FWL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same	8. FARM OR LEASE NAME Federal
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	9. WELL NO. 100-A
	10. FIELD OR WILDCAT NAME Blanco Mesa Verde
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27-T31N-R11W N.M.P.M.
	12. COUNTY OR PARISH San Juan
	13. STATE N.M.
	14. API NO. 30-045-25851
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5801' G.R.

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) See Below

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

RECEIVED  
AUG 07 1986

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Work completed as requested in letter of February 12, 1986  
(Copy enclosed)

ACCEPTED FOR RECORD

AUG 07 1986

FARMINGTON RESOURCE AREA  
FARMINGTON, NEW MEXICO

Subsurface Safety Valve: Manu. and Type

FOR: BASIN MINERALS, INC.

18. I hereby certify that the foregoing is true and correct

SIGNED EWELL N. WALSH

President, Walsh Engr.

Ewell N. Walsh, PE

TITLE & Prod. Corp.

DATE 8/6/86

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE



# United States Department of the Interior

## BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA

Caller Service 4104  
Farmington, New Mexico 87499

IN REPLY REFER TO:  
SF-078097 (WC)  
3162.5-1a (016)

FEB 12 1986

AUG 11 1986  
OIL CON. DIV.  
DIST. 3

CERTIFIED--RETURN RECEIPT REQUESTED

Basin Minerals Inc.  
c/o Walsh Engineering and Production Corporation  
P. O. Drawer 419  
Farmington, NM 87499

Dear Mr. Walsh:

On January 29, 1986, the following Basin Minerals wells were inspected and the following deficiencies were noted:

Lease No. SF-078097, well No. 100-A Federal, 950' FSL and 1005' FWL, sec. 27, T. 31 N., R11 W., San Juan County, New Mexico.

1. Wire cable needs to be removed from the location.
2. All above ground equipment must be painted green.
3. East side of pad must be reworked so that the slope is decreased to minimize erosion.
4. Any area of the well pad not needed for production must be seeded by drill with BLM Seed Mix No. 2. This must be done between July 15 and September 15, 1986.


Lease No. SF-078097, well No. 1 Federal, 790' FSL and 1750' FWL, sec. 27, T. 31 N., R. 11 W., San Juan County, New Mexico.

1. Southeast side of pad must be reworked so that the slope is decreased to minimize erosion.
2. Any area of the well pad needed for production must be seeded by drill with BLM Seed Mix No. 2. This must be done between July 15 and September 15, 1986.

We should be notified by letter or Sundry Notice when the **surface** restoration is completed. We will schedule an inspection to check the **well**site after the grass has had a chance to become established.

If you have any questions, please contact the Fluids Surface Management Staff at (505) 325-4572.

Sincerely,

  
John Miller  
Area Manager



P. O. BOX 3235 • FARMINGTON, NEW MEXICO 87499

INVOICE  
NUMBER 7-171  
INVOICE  
DATE 07-25-86  
PLEASE REFER TO ABOVE INVOICE  
PLEASE REFER TO ABOVE INVOICE  
NUMBER ON PAYMENTS OR COR-  
RESPONDENCE.

Sold To: BASIN MINERALS, INC.

Date 07-24-86

Your Order No. \_\_\_\_\_

Charge: FEDERAL #100-A + FEDERAL #1

DESCRIPTION OF WORK Labor, equipment, and materials.  
Haul equipment to location, set and painted tank,  
strawny, and landing. Also, painted well-head  
and production unit. Re-worked slopes and seeded.  
Broke out blow-line and back-fill pit. Clean-up  
trash around location. Loaded tubing & hauled to  
Cyster Well Service yard & unloaded. Return to yard.

	HRS.	RATE	EXT.
<u>PUSHER</u>			
<u>RSTBT.</u>			
<u>RSTBT.</u>			
<u>RSTBT.</u>			
<u>RSTBT.</u>			
<u>RSTBT.</u>			
<u>EQUIPMENT</u>	UNIT NO.		
<u>2 1/2 Ton Truck</u>			
<u>Backhoe w/operator</u>			
<u>3/4 Ton Pickup w/paintsig</u>			
<u>Seed Drill</u>			

Sub-Total-

Materials #2 seed mix  
paint & thinner

Sub-Total

Tax

APPROVED BY [Signature]

DATE 8-5-86

850.00  
42.50  
892.50

TOTAL  
STATE: NM CO.: SS LOADED MILES: \_\_\_\_\_ EMPTY MILES: \_\_\_\_\_

As per Bill

TICKET

AUTHORIZED BY

TERMS: NET DUE 30 DAYS FROM DATE OF INVOICE

San Juan repro Form 274-1

1887

San Juan Reproduction Co., Farmington, N.M.