

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME N/A
2. NAME OF OPERATOR WINTERSHALL CORPORATION	8. FARM OR LEASE NAME UTE
3. ADDRESS OF OPERATOR 5251 DTC Parkway, Suite 500, Englewood, CO 80111	9. WELL NO. 34-44
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1090' FSL & 790' FEL (SESE)	10. FIELD AND POOL, OR WILDCAT BASIN DAKOTA
14. PERMIT NO.	11. SEC., T., R., M., OR B.L. & SURVEY OR AREA 34-31N-14W NMPM
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5,612' ungraded ground	12. COUNTY OR PARISH San Juan
	13. STATE NM

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACURE TREAT	<input type="checkbox"/>	FRACURE TREATMENT	<input checked="" type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

RECEIVED
Bureau of Land Management

5/27/87 MI Completion Rig.
5/28/87 Ran CBL-VDL, GR & CCL from 6054'-4650'
5/30/87 Perforate Burro Canyon from 5980-5988' w/ 2 JSPF **Durango, Colorado**
Pumped 1000 gals 15% HCL w/ 1 gal HAI-60 + 2 gal Losurf 300.
to frac well. Swabbed.
5/31/87 Spotted 250 gals 7-1/2% HCL from 5900-5650'.
6/1/87 Perf 5822'-5898'. A total of 15 holes. Pumped 1000 gals 15%
HCL w/ 1 gal HAI-60 & 1 gal Losurf. Fraced w/ 82,430 gal slick
water & 52,500# 20/40 mesh sand. Began swabbing operation.
6/2/87 - 6/4/87 Swabbing.

RECEIVED

OCT 29 1987

ACCEPTED FOR RECORD

JUN 8 1987

OIL CON. DIV.] *Montrose*

DISTRICT *Scott*

18. I hereby certify that the foregoing is true and correct

SIGNED

David T. Howell

TITLE

Operations Manager

DATE

6/4/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DURANGO OFFICE COPY

*See Instructions on Reverse Side