


UTE MOUNTAIN UTE 34-11

The following is a tabulation of all deviation surveys ran on the Ute Mountain Ute 34-11 well.
The well is located 945' FNL and 1110' FWL (NWNW) Sec. 34; T31N; R14W; NMPM San Juan County, New Mexico.

Depth (Ft)	Deviation	Depth(Ft)	Deviation
115	1/2	2867	2 1/2
210	3/4	2991	2 1/2
494	1 1/4	3115	2
703	2	3230	2 1/4
797	1 3/4	3355	2 1/4
884	2 1/2	3608	2
914	2 1/4	3740	2 1/4
945	1 3/4	3855	2 1/2
975	1 3/4	3945	2 3/4
1008	2	4005	3
1106	2	4080	3
1168	2	4173	2 3/4
1262	2	4257	2 3/4
1325	2	4380	2 1/4
1388	2 1/2	4515	2 1/2
1451	2 1/2	4605	2 3/4
1504	2 1/2	4748	3 1/4
1575	2 1/2	4810	3 1/4
1577	2 1/2	4872	4
1638	3	4900	4
1670	Misrun	4940	4 1/8
1730	3	4975	4
1793	3 1/4	5069	4
1823	3 1/4	5153	4
1855	3	5214	3 1/2
1918	2 1/2	5351	3 1/2
2022	2 1/4	5466	3 1/2
2117	2 1/2	5560	2 3/4
2209	2 1/2	5693	2 1/2
2294	3	5825	2 1/2
2356	2 3/4		
2450	2 1/2		
2544	2 1/4		
2635	2		
2740	2		


I, Fred J. Clausen, Area Superintendent for Wintershall Corporation, do here by attest that I have inspected the above surveys and found the same to be accurate, valid and complete to the best of my knowledge.


Fred J. Clausen
Area Superintendent

State of Colorado

County of Montezuma

Subscribed and sworn to me this 3rd day of December, 1987


Notary Public

My commission Expires: 06/01/91

RECEIVED
DEC 04 1987
OIL CON. DIV.
DIST. 3