

F

30-045-28352

10-25-90

F. loc. 940/S:840/W Elev. 6192 GL Spd. Comp. TD. PB.
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
 Csg. Perf. Prod. Stim.

T Gas
R
A
N
S

BO/D Grav. 1st Del. Gas
 MCF/D After Hrs. SICP PSI After Days GOR 1st Del.

TOPS	NITD	X	Well Log	TEST DATA						
Ojo Alamo	C-103		Plot X	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland	C-104		Electric Log							
Fruitland			C-122							
Pictured Cliffs	Ditr		Dfo							
Chacra	Datr		Dac							
Cliff House	S/308.84 Acres									
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

P
 o
 o
 Basal FrtCoal

Co. SJ s 3 T 31N R10W UM Oper. Meridian Oil, Inc. Les. Lucerne A

No 100

LUCERNE A #100

M-03-31N-10W

MERIDIAN OIL, INC.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401

TAKE
PRIDE IN
AMERICA

IN REPLY REFER TO
SF-078389 et al. (WC)
3162.3-1.0 (019)

DEC. 4 1991

RECEIVED
DEC 5 1991
OIL CON. DIV
DIST. 3

Meridian Oil Inc.
PO Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill the following wells:

- ✓ 1. No. 101 Lucerne A Com, Sec. 9, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- ✓ 2. No. 265 Rosa Unit, Sec. 27, T. 31 N., R. 5 W., Rio Arriba County, New Mexico, lease SF-078770.
- ✓ 3. No. 500 Summit Viles, Sec. 33, T. 29 N., R. 11 W., San Juan County, New Mexico, lease SF-047019-A.
- ✓ 4. No. 213 San Juan 32-9 Unit, Sec 14, T. 31 N., R. 10 W., San Juan County, New Mexico, lease NM-01594.
- ✓ 5. No. 102 Lucerne A, Sec 9, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- ✓ 6. No. 100 Lucerne A, Sec 3, T. 31 N., R. 10 W., San Juan County, New Mexico, lease SF-078389.
- ✓ 7. No. 500 Angel Peak B, Sec 13, T. 28 N., R. 11 W., San Juan County, New Mexico, lease SF-047017-A.
- ✓ 8. No. 101 East, Sec 25, T. 31 N., R. 12 W., San Juan County, New Mexico, lease SF-077652.
- ✓ 9. No. 8R Atlantic A, Sec 29, T. 31 N., R. 10 W., San Juan County, New Mexico, lease NM-0606.

As discussed with Peggy Bradfield of your company on, November 20, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that

ABANDONED LOCATION

construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

9 Enclosures

cc:
New Mexico Oil Conservation Division, Aztec, NM

