H & H Wireline Service, Inc.

P. O. Box 899, Flora Vista New Mexico 87415

APRIL 14. 1998

PHILLIPS PETROLEUM COMPANY 5525 HWY 64 NBU 3004 FARMINGTON, NEW MEXICO 87401 OIL COM. DIV.

WELL NAME: SAN JUAN 32-7 # 86 _ 8-34-33N-7 W

TYPE TEST: TEMP-SURVEY

PICTURE CLIFF

FORMATION: COUNTY:

SAN JUAN

STATE:

NEW MEXICO

ATTENTION: MR. HAROLD ELLEDGE

GENTLEMEN:

ATTACHED YOU WILL FIND THE RESULTS OF THE ABOVE CAPTIONED TEST OF TEMP-SURVEY ON THE ABOVE CAPTIONED WELL WHICH ARE IN TABULAR & GRAPHICAL FORM.

IT HAS BEEN OUR PLEASURE TO CONDUCT THIS SERVICE FOR YOU. WE ARE LOOKING FORWARD TO SERVING YOU IN THE FUTURE.

THANK YOU.

H & H WIRELINE SERVICE, INC.

ARCHIE HUGHES & DONNA HUGHES

PRESIDENT

PHILLIPS PETROLEUM COMPANY 5525 HIGHWAY 64 NBU 3004 FARMINGTON. NEW MEXICO 87401

DATE: 04-14-98

SURVEY RAN @ 10:48

WELL NAME: SAN JUAN 32-7 # 86

FIELD: SAN JUAN COUNTY: SAN JUAN STATE: NEW NEXICO

TEST TYPE: TEMERATURE SURVEY

REASON: FIND CEMENT TOP @ 263'

ELAPSED TIME MIN'S	DEPTH IN FEET	TEMPERATURE DEGREES F.
/***		
START SURVEY 0.0	0	76.8
11:08 2.0	100	76.8
4 . ()	200	76.8
Cor English	263	76 . 8
6.0	300	77.9
8.0	400	80.7
10.0	500	87.8
12.0	600	89.4
14.0	700	90.8
16.0	800	85.2
18.Q	900	93.7
20.0	1000	102.6
22.0	1100	91.4
24.0	1200	89.0
26.0	1300	87.1
28.0	1400	89.0
30.0	1500	88.5

H & H WIRELINE SERVICE, INC. P. O. BOX 899 FLORA VISTA. NEW MEXICO 87415 OPERATOR: CHARLES HUGHES UNIT #: T-10

TEMERATURE IN DEGREES F.

