

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Consolidated Oil & Gas Inc. P.O. Box 2038 Farmington, New Mexico
(Address)

LEASE Robinson Bros. WELL NO. 1-34 UNIT P S 34 T 32 N R 13 W

DATE WORK PERFORMED 8-3-64 POOL Mesaverde & Dakota

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☒ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

This well has a casing failure. The tubing was pulled, leaving 1 joint and a 6' sub and a locator seal assembly in the metal "D". We ran a casing inspection log. The log shows holes and questionable pipe from 3750' to 3875'. The fish will be recovered and the bad pipe will be squeezed with approximately 300 ft³ of cement. After testing the pipe and cleaning up the well it will be put back on the line.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. 5803 KB. TD 6886 PBD 6876 Prod. Int. 4445-6872 Compl Date 6-5-61
Tbng. Dia 1" & 1 1/2" Tbng Depth 4480 & 6611 Oil String Dia 5 1/2" Oil String Depth 6888
Perf Interval (s) 4445' - 4692 Mesaverde 6657' - 6872' Dakota
Open Hole Interval _____ Producing Formation (s) Mesaverde & Dakota

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name A. R. Kendrick
Title PETROLEUM ENGINEER DIST. NO. 3
Date AUG 5 1964

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Thomas M. Boyd
Position Area Superintendent
Company Consolidated Oil & Gas Inc.

STATE OF NEW YORK
OIL CONSERVATION COMMISSION
ALBANY OFFICE
NUMBER OF COPIES