



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency \_\_\_\_\_

Allottee \_\_\_\_\_

Lease No. \_\_\_\_\_

NAVAJO TRIBAL 14-20-603-586

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SEPTEMBER 24, 1963

HORSESHOE  
Well No. 1 is located 330 ft. from N line and 660 ft. from E line of sec. 32  
SE SE 32 32N 17W NWP  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
HORSESHOE CANYON EXT. SAN JUAN NEW MEXICO  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5348 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Plugged and abandoned September 21, 1963.

Scott Drilling Company placed 37 sx regular cement in the 6-1/4" hole over the Gallup formation amounting to approximately 200 feet at the bottom of hole from 1000-1200. Cemented 7-5/8" surface casing and installed regulation dry hole marker therein.

U. S. GEOLOGICAL SURVEY  
DEPT. OF THE INTERIOR

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company CURTIS J. LITTLE

Address 2929 MONTE VISTA, NE  
ALBUQUERQUE, NEW MEXICO

By [Signature]  
Title OPERATOR



