

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Bureau

100-1

Allottee Bureau

Lease No. 11-20-60-700

SUNDRY NOTICES AND REPORTS ON WELLS

18 1959

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 17, 1959

Well No. 4 is located 1400 ft. from S line and 990 ft. from E line of sec. 30
22.4 Section 30 (1/4 Sec. and Sec. No.) 22E (Twp.) 13W (Range) R. 2. P. 1. E. (Meridian)
Shimmy Rock (Gallup Nat.) (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5531 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Work in hole with open-ended drill pipe & spotted cement plugs as follows:
1421'-1429' - 70 lbs., 3-inch cement plug in top of 2-1/8" casing at surface.

All spaces between plugs filled with heavy mud-laden fluid. Set 4" pipe marker in top of 2-1/8" casing & extending 4' above ground level.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY
Box 426
 Address Farmington, New Mexico

By (Signed) P. E. Cosper

Title District Superintendent

