

(SUBMIT IN TRIPLICATE)

Indian Agency **Consolidated Sta**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____
Lease No. **15-22-604-1942**

			X

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	RECEIVED JUL 11 1961 U. S. GEOLOGICAL SURVEY DURANGO, CO.
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 1, 1961


Well No. **1** **Ute Mountain** is located **200** ft. from **[N]** line and **200** ft. from **[E]** line of sec. **36**
NE NE **36** **32N** **19W** **100W**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **San Juan** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6741** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

1. Cemented 102' of 10-3/4" surface casing with 50 lbs circulated by Halliburton to surface.
2. Set 8-1/8" temporary water shut off casing at 1743'. Water shut off successful. Hole dry.
3. Set 8-1/2" temporary water shut off casing at 2971'. Water shut off successful. Hole dry.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Summit Oil Corp.**

Address **2127 San Mateo NE**
Albuquerque, New Mexico

By **Bob Doregan**
 Title **Geologist**