

(SUBMIT IN TRIPLICATE)


UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Indian Agency \_\_\_\_\_

Navajo Tribal \_\_\_\_\_

Allottee Navajo "M" \_\_\_\_\_

Lease No. 14-20-603-3013



## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	<b>RECEIVED</b> <b>AUG 4 1959</b> <b>U.S. GEOLOGICAL SURVEY</b> <b>FARMINGTON, NEW MEXICO</b>
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 31, 1959

Well No. 2 is located 1900 ft. from S line and 1900 ft. from W line of sec. 33

SW 1/4 Section 33 13N 17W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Shimney Rock ( Gallup Nat. ) San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5300 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well has been drilled to a Total Depth of 124' and fully tested without encountering any commercial oil or gas pay. Well to be plugged as follows: 120' - 1099' with 15 sacks cement. Will run free point indicator, cut off and pull 9" CD casing. Will set 25 sack cement plug where casing is cut off. 5 sack cement plug to be set in top of 8-5/8" CD surface casing with 4" pipe marker extending 4' above ground level.

Verbal approval has been given to do this work by Phil McGrath.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY

Box 426

Address Farmington, New Mexico

By (Signed) P. E. Cosper

Title District Superintendent