Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89 District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs NM 88241-1980 2040 Pacheco St. 30-045-11201 Santa Fe, NM 87505 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE [ STATE X DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 B111-24-24 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" Wright State Com (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: GAS WELL WELL OTHER 8. Well No. 2. Name of Operator Taurus Exploration, U.S.A., Inc. 9. Pool name or Wildcat 3. Address of Operator Basin Dakota 2198 Bloomfield Highway; Farmington, NM 87401 4. Well Location North 1000 Line and Feet From The San Juan 32 North 13 West 36 NMPM Township Range Section 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5847 GL Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: **NOTICE OF INTENTION TO:** ALTERING CASING REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS CHANGE PLANS TEMPORARILY ABANDON CASING TEST AND CEMENT JOB PULL OR ALTER CASING OTHER: -OTHER: -12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4/10/98 MIRU. TOH and laydown MV tubing string. Tie onto Dakota - could not pump in at 1000 psi. 4/13/98 Release seal assembly and TOH. TIH and set CIBP at 6400'. Cap plug with 70 sks Class B cement 6400' - 5800'. TOH (procedure approved verbal by Ernie Bush). 4/14/98 TIH w/packer. Isolate casing leak at 399'. TOH. TIH and set RBP @2200'. TOH. Perf 2 Squeeze holes at 400'. Squeeze cement with 120 sks Class G cement circulate to surface. WOC. 4/15/98 TIH and clean out to 2200'. Test casing to 500# for 30 min. OK. TIH. and recover RBP. Ran 159 joints 2 3/8" 4.7# tubing set at 4776'. Well now single MV. at the information and complete to the best of my knowledge and belief. I hereby certify TITLE Production Supetintendent 4/16/98 \_ DATE \_ TELEPHONE NO. 505-325-6800 TYPE OR PRINT NAME Ga

(This space for State Use)

Robinson

DEPUTY OIL & GAS INSPECTOR, DIST. #3