(*SUBMIT IN TRIPLICATE*)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency **Navajo**

Window Rock, Arizona

Allottee _____

Lease No. **14-20-600-586**

		0
32		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

RECEIVED FEB 2 1959

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 12, 19**59**

Well No. **1-32** is located **600** ft. from {N/S} line and **560'** ft. from {E/W} line of sec. **32**

Unit I, SEC. 32
(¼ Sec. and Sec. No.)

32N (Twp.)   **17W** (Range)   _____ (Meridian)

Unnamed (Field)

San Juan County (County or Subdivision)

New Mexico (State or Territory)

The elevation of the derrick floor above sea level is **5444** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2 jts. 86' T"-32/-J55-8rd. thd. at & c R-2 smls. csg. set@ 71' cmtd w/20 sx reg. cmt.
Cmt. circulated.
Top Lecite 960'
Top Samestee 1105'
T.D. 1145 Drlr. 1150' Schlumberger
60 sx. plug 900' to 1100' by pump method through drill pipe, 20 sx. plug in surface csg. w/4" pipe marker.

RECEIVED FEB 3 1959 OIL CON. COM. DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations maybe commenced.

Company **Murphy Corporation**

Address **940 Petroleum Club Building**

Denver 2, Colorado

By *Claude O. Huckley*

Title **Production Supt.**