

(SUBMIT IN TRIPLICATE)

	27	
X		

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo Tribal

Allottee _____

Lease No. 14-20-603-5012

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED
AUG 25 1962
U.S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO


Well No. 1-27 is located 686 ft. from SW line and 492 ft. from W line of sec. 27
SW SW 27 32N 17W NMP
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5482 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plan to cement 1082-1282 (200') of the 6-1/4' hole with 37 sacks regular cement and cement the 7" surface casing with 3 sacks with regulation dry hole marker installed in the surface casing.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____

Address 2929 Monte Vista NE

Albuquerque, New Mexico

By Curtis J. Little
Curtis J. Little

Title Owner