

	27	
x		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R359.4.

Indian Agency Navajo Tribal

Allottee 14-20-603-5012

Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS **RECEIVED**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

AUG 30 1962

U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 28, 1962

Well No. 1-27 is located 686 ft. from S line and 492 ft. from W line of sec. 27
SW SW 27 (4 Sec. and Sec. No.) 32N (Twp.) 17W (Range) MP (Meridian)
Wildcat (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5482 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged and abandoned August 28, 1962.
 Scott Drilling Company placed 37 sacks regular cement in the 6-1/4" hole over the Gallup formation amounting to approximately 200 feet at the bottom of hole from 1082-1282. Cemented 7" surface casing with 4 sacks regular and installed regulation dry hole marker therein.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company _____

Address 2929 Monte Vista NE

Albuquerque, New Mexico

By Curtis J. Little
 Title Owner