

(SUBMIT IN TRIPLICATE)

Indian Agency ~~Indian Agency~~

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____

~~1-10-1959~~

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

~~November 16~~, 19 ~~59~~


Well No. ~~1~~ is located ~~750~~ ft. from ~~SW~~ line and ~~500~~ ft. from ~~E~~ line of sec. ~~25~~
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
~~Well No.~~ (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is ~~5000~~ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Failed rock and tubing, no recovery of Production Casing.
Set 1st plug from 3200' to 3300' with 15 sacks cement.
Set plug from 3300' to 3400' with 15 sacks cement.
Plugged 4" Barker above ground level.
Well plugged and abandoned 11/21/59.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ~~Arden Oil and Gas Company~~

Address ~~Box 1702~~

~~Farmington, New Mexico~~

By ORIGINAL SIGNED BY JOE C. SALMON

Title ~~Natural Gas Superintendent~~

