

(SUBMIT IN TRIPLICATE)

Indian Agency **NAVAJO TRIBAL**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. **14-20-603-5012**

	21	

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	RECEIVED FEB 5 1963 U. S. GEOLOGICAL SURVEY FARMINGTON, NEW MEXICO
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

JANUARY 26, 19**63**

Well No. **NAVAJO 2-21** is located **1970** ft. from **S** line and **690** ft. from **W** line of sec. **21**


NW SW 21 (1/4 Sec. and Sec. No.)	32N 17W (Twp.) (Range)	NMP (Meridian)
UNDESIGNATED (Field)	SAN JUAN (County or Subdivision)	NEW MEXICO (State or Territory)

The elevation of the derrick floor above sea level is **5997** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud 1-24-63 at 9 A. M.
Set 32' of 8-5/8" casing with 6 sx regular.
Encountered no surface water.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **CURTIS J. LITTLE**

Address **2929 MONTE VISTA, NE**
ALBUQUERQUE, NEW MEXICO

By *[Signature]*
Title **OPERATOR**