			- (·) (、	-21	Mes	well)	
Form 9-331 (May 1963)		STATES	SUBMIT IN T	RIPLICATE*	Form approv	red. au No. 42-R1424.	
(3.24) 22000,	DEPARTMENT OF	THE INTERIO	R verse side)	11024 OH 14	5. LEASE DESIGNATION	AND SERIAL NO.	
	GEOLOGIC	CAL SURVEY			14-20-603	- 583	
CHI	NDRY NOTICES AN	ID REPORTS O	N WELLS		6. IF INDIAN, ALLOTTE	E OR TRIBE NAME	
	s form for proposals to drill of Use "APPLICATION FOR I			ervoir.			
	Use "APPLICATION FOR I	PERMIT—" for such pro	posals.)		<u>Navajo</u>	1	
OIL GAB					7. UNIT AGREEMENT N	AMB	
WELL WELL  2. NAME OF OPERATOR	OTHER .		· · · · · ·	<del></del>	S. FARM OR LEASE NA	ME	
ARI-MEX OIL AND EXPLORATION. Inc.  3. ADDRESS OF OPERATOR C/O Walsh Engineering & Production Corp.					Navajo 9. WELL NO.		
P. O. Box 254, Farmington, N.M. 87401					5		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					10. FIELD AND POOL,	OR WILDCAT	
See also space 17 below.) At surface					Mesa Gallu	ın	
440'FSL, 1980'FEL					11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
					Sec.10-T32N-R18W		
					N.M.F		
14. PERMIT NO.	15. ELEVAT	IONS (Show whether DF,	RT, GR, etc.)		12. COUNTY OR PARIS	H 18. STATE	
					San Juan	New Mex.	
16.	Check Appropriate	Box To Indicate No	ature of Notice F	Report, or C	Other Data		
	•••	1			DENT REPORT OF:		
	NOTICE OF INTENTION TO:	<u></u> -				<del></del>	
TEST WATER SHUT	-OFF PULL OR ALT	ER CASING	WATER SHUT-O		REPAIRING		
FRACTURE TREAT	MULTIPLE CO	MPLETE	FRACTURE TRE		ALTERING	<del></del>	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR	hut in	ABANDONMI condition	X	
REPAIR WELL (Other)	CHANGE PLAN	's	(Note: ]	Report results	of multiple completion letion Report and Log for	on Well	
gas well	d is indicated in an oil poole at this time	l. A gas lin	ie connecti	on is i	not		
		MAY 26 OIL CON. DIST.		U. Q		7 √ 	
18. I hereby certify it	RI-MEX OIL AND the foregoing is true and WALSH, P.E. ederal or State office use)		Inc. esident, Wa Producti <b>o</b> n			ay 24, 1976	

DATE \_\_\_