



STATE OF NEW MEXICO

ENERGY, MINERALS and NATURAL RESOURCES DIVISION  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE



BRUCE KING  
GOVERNOR

ANITA LOCKWOOD  
CABINET SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

July 23, 1993

Ms. Susan Dolan  
Meridian Oil Inc.  
PO Box 4289  
Farmington, NM 87499

RE: MOI Lindsey #2A, J-11-30N-09W (Blow pit)  
MOI Johnston Federal #7, A-07-31N-09W (Tank Drain pit)  
SRC Decker #4A, O-10-32N-12W (Separator pit)  
SRC Hillstrom #1A, E-35-32N-12W (Drip pit)

Dear Susan:

Field inspections conducted on July 21, 1993 by Denny Foust revealed that the above mentioned pits have been cleaned out or replaced with below grade fiberglass tanks as per requested. The pits are now in compliance. Enclosed please find copies of the approved C-134's.

If you have any questions please feel free to call this office.

Yours truly,

*Dianna K. Fairhurst*

Dianna K. Fairhurst  
Deputy Oil & Gas Inspector

xc: Don Ellsworth - BLM Farmington  
C-134 Correspondence  
Well File  
Gary Osborne - MOI  
Noel Rogers - MOI

Submit 4 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-134  
Aug. 1, 1989

DISTRICT I

P.O. Box 1980, Hobbs, NM 88241-1980

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II

P.O. Drawer DD, Artesia, NM 88211-0719

Permit No. 1729  
(For Division Use Only)

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

APPLICATION FOR EXCEPTION TO DIVISION ORDER R-8952  
FOR PROTECTION OF MIGRATORY BIRDS Rule 8(b), Rule 105(b), Rule 312(h), Rule 313, or Rule 711(I)

Operator Name: Southland Royalty Company

Operator Address: P. O. Box 4289, Farmington, New Mexico 87499

Lease or Facility Name: Hillstrom #1A Location: E 35 32N 12W  
Size of pit or tank: Drip 15 x 15 Ut. Ltr. Sec. Twp. Rge.

Operator requests exception from the requirement to screen, net or cover the pit or tank at the above described facility.

☒ The pit or tank is not hazardous to migratory waterfowl. Describe completely the reason pit is non-hazardous.

The pit does not contain any substance hazardous to migratory waterfowl.

1) If any oil or hydrocarbons should reach this facility, give method and time required for removal:

Immediately following discovery, oil or hydrocarbons would be removed by a vacuum truck.

2) If any oil or hydrocarbons reach the above-described facility, the operator is required to notify the appropriate District Office of the OCD within 24 hours.

Operator proposes the following alternate protective measures:

CERTIFICATION BY OPERATOR: I hereby certify that the information given above is true and complete to the best of my knowledge and belief.

Signature Louis D. Jones Title Acting Production Mgr. Date October 1, 1989

Printed Name Louis D. Jones Telephone No. 505-326-9700

FOR OIL CONSERVATION DIVISION USE

Date Facility Inspected 1/5/93


Inspected by Sianna J. Fairhurst

Approved by

Title

Date

7/21/93 INSPECTED BY DENNY FOUST  
PIT IS NOW DRY



NOT APPROVED

PIT CONTAINS H<sub>2</sub>O THAT  
IS A RUSSIAN ORANGE COLOR - NO NET