well

2. NAME OF OPERATOR

AT TOTAL DEPTH:

3. ADDRESS OF OPERATOR

AT SURFACE: T-32-N AT TOP PROD. INTERVAL:

REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

other

501 Airport Drive Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

<u>Same</u>

R-14-W

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.

1040' FSL x 810' FWL, Section 24,

SUBSEQUENT REPORT OF:

gas

well

 \mathbf{x}

AMOCO PRODUCTION COMPANY

5. LEASE
MOO-C-1420-0627
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
Ute Mountain Tribe
8. FARM OR LEASE NAME
Ute Mountain Tribal "L"
9. WELL NO.
2
10. FIELD OR WILDCAT NAME
Undesignated Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR
AREA SW/4 SW/4 Section 24,
T-32-N, R-14-W
12. COUNTY OR PARISH 13. STATE
Rio Afriba NM
14. API NO.

30-045-22949

6771 GL.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

6784 KB

SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zone REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES** ABANDON* (other) Surface Casing 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Spudded 12-1/4" hole on 4/16/78. Drilled to 295'. Set 8-5/8" 24#, K-55 casing at 295' with 300 sx Class "B". Circulated 35 sx good cement. Pressure tested to 500#; held OK.

CONDITIONS OF APPROVAL, IF ANY:



APR 2 5 1978