## **UNITED STATES**

UNITED STATES			LEASE	14-20-604	-62	(cons /	
DEPARTMENT OF THE INTERIOR				22-IND-619		(	
GEOLOGICAL SURVEY			6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
			Ute 1	Mountain '	Cribe	e .	
SUNDRY NOTICES AND REPORTS ON WELLS			7. UNIT AGREEMENT NAME Development				
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)							
				R LEASE NAM	-21	<u> </u>	
1. oil gas 🛪			I	Jte India	as 🖑	A'' 5 🚆	
well well other			WELL N	0. 그들은 그	1.9	<u> </u>	
2. NAME OF OPERATOR				= 5 12	₹ 	<b>3</b> - C	
AMOCO PRODUCTION COMPANY		10.	FIELD C	R WILDCAT N	AME	æ, . €	
3. ADDRESS OF OPERATOR			Ute	e Dome ື⊸ ີ	<u>Jako</u> 1	ta 🔻 💍	
501 Airport Drive Farmir	ngton, NM 87401	11.		, R., M <sub>7</sub> OR B			
4. LOCATION OF WELL (REPORT LOCAT	ION CLEARLY. See spa	ace 17		SW/4- NE/14		ction 3	6,
below.) 1840 FNL x 2310	)' FEL, Section	36,		Γ-32-N° :R			
AT SURFACE: T-32-N, R-14-W		12.		Y OR PARISH		STATE	
AT TOTAL DEPTH: Same			San .	Juan 🦠 🥇 🗟 📗	<u>5</u>	NM -	
заше			API NO.		⊒.	10,10	
16. CHECK APPROPRIATE BOX TO INDI	CATE NATURE OF NO	OTICE,	· · · · · · · · ·	30-045= <i>2</i> :2	95 <b>0</b> :	<u> </u>	
REPORT, OR OTHER DATA		15.	<b>ELEVAT</b>	IONS (SHOW			WD)
	DOFOUGHT DEDOOT	,		6277 'S GL.	6 <u>29</u> 0	0 <sup>\$</sup> ₹\$B	
·	BSEQUENT REPORT (	OF:		10 de	<u></u>	10.10	
TEST WATER SHUT-OFF	H			andu Amerika Anta Amerika Amerika Amerika Amerika Amerika Amerika Amerika Amerika Amerika Amerika Amerika Anta Amerika Anta Amerika Amerika Amerika Amerika Anta Amerika Anta Anta Anta Anta Anta Anta Anta Ant	Ď	<b>5</b> ≥ 5 €	
FRACTURE TREAT	H			3 C C C C C C C C C C C C C C C C C C C	biuo	흑중출호	
REPAIR WELL	Ħ	(N	OTE: Rep	_ ು ನ್ನ ort results of mu	iltiple c	ominietion o	r zone
PULL OR ALTER CASING		•	char	nge on Form 9-	330.)_	3 5 5	. 20110
MULTIPLE COMPLETE	· <b>□</b>		ā		<u> </u>	25	7
CHANGE ZONES				<b>425</b>	₽.	- <b>ខ្</b> ងឺក៏ក្ន	-
ABANDON*			Ã.		Ö		
(other) <u>Completion-Perf &amp; Fi</u>	cac		-	្តាស់ ទីញីដី ដី	# #	Dir.	~
17. DESCRIBE PROPOSED OR COMPLETE	D OPERATIONS (Clea	rly state all I	pertinent	details, and	give (	pertinent c	lates,
including estimated date of starting a	ny proposed work. If w	vell is directio	nally dri	illed, give sub	surfac	e locations	s and
measured and true vertical depths for					الد	3 7 6 6	_
Completion operations con	mmenced on 5/9/	/8. Tripp	ed in	witer tub	ing	and bit	. •
Cleaned out to 2740' PBD.	. Perforated 2	550-2642	. Fr	aced with	1 1/2	,ĕŲU⊰ ±ο	s.
sand and 86,300 gallons i		ipped in	with	tubing⊹an	g 1827.	rai Ote	ane
out frac sand and fluid t	to PBD.				35	is the	
				900 901 901 100 100 100 100 100 100 100	îv	[-	
Production tubing landed	at 2646'.			the add	on na Suite requirements	will be going in going going	
				=	513		
Completion rig released of	on 5/11/78.			ing pring park ing park ing park ing park park park park park park park park	E.	8 01 00 00 00 00 00 00 00 00 00 00 00 00	
•				functions included in the state of the state	per	ristom overco overco swith	
				o gbb suins succi sucul	<u> </u>		
•				ឧត្តសិគ្គ	ALIA MINE	English Hallowin Hallowin	
				W S S S	52	<u> </u>	
					5	5 <b>5</b> 7	
Cubaudaaa Cafabi Valua Manu and Tuna				2 2 2 2 2 2 3 3 4 4 4 4 4 4 4 4 4 4 4 4	<sub>് -</sub>	5 TO 10	Ft.
Subsurface Safety Valve: Manu. and Type		•			ــــــ س	<u> </u>	rt.
18. I hereby certify that the foregoing is tru	e and correct			10 ; 10 ; 10 ;	7 O	C , .	
f f allong	Araa Ad	m. Supvr.		5924	/78	1, 10, 10, 10, 10, 10, 10, 10, 10, 10, 1	
SIGNED E. E. SVOSODA	TITLE ATEA AG	Dupvi	DATE .		<del>, , , , , , , , , , , , , , , , , , , </del>		
	(This space for Federal or	State office use	)	Consideration of the considera	ο :	4 7 9 1	
				DY K	<u> </u>		
APPROVED BY	TITLE		DATE		-		
				Front Control	E 1	MET	$\mathcal{T}$
				7 7 CA	<b>E</b>	V ibə 41	1

\*See Instructions on Reverse Side

MAY 2 6 1978