MULTIPLE COMPLETE CHANGE ZONES ABANDON\* (other)

4.

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Dec. 1973	Budget Bureau No. 42-11424
UNITED STATES  DEPARTMENT OF THE INTERIOR	5. LEASE SF 078147
GEOLOGICAL SURVEY  SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
1. oil gas X other	Moore 9. WELL NO.
2. NAME OF OPERATOR	4A
El Paso Natural Gas Company  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Blanco MV
Box 289, Farmington, New Mexico 87401  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23, T-32-N, R-12-W N.M.P.M.
AT SURFACE: 1640'S,910'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH San Juan New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	

gas well X well other 2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1 below.) AT SURFACE: AT TOP PROD. INTER AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6419' G.L. REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (NOTE: Report results of multiple completion or zone PULL OR ALTER CASING change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

PBTD 5637'. Tested casing to 3500#, OK. Perfed 5130,5137,5238,5244,5250, 7-29-79: 5256,5262,5268,5292,5298,5303,5315,5321,5325,5343,5352,5361,5417,5426,5446,5467, 5480,5492,5503,5526,5571' W/1 SPZ. Fraced w/85,000# 20/40 sand,170,000 gal. water. Flushed w/6676 gal. water.

RECEIVE Subsurface Safety Valve: Manu. and Type \_ U. S. GEOLOGICAL SURVEY 18. I hereby certify that the foregoing is true and correct FARMINGTON, N. M. TITLE Drilling Clerk July 30, DATE (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

