

F

30-045-24149

12-20-79

F. Loc. 1390/S; 890/E Elev. 6071 GL Spd. 5-17-80 Comp. 1-15-81 TD 7109 PB 6830

Casing S. 9 5/8 @ 372 W 300 Sx. Int. @ W Sx. Pr. 7 @ 7105 W 2315 Sx. T. 2 1/16 @ 6773
Csg. Perf. 5968-6260 Prod. Stim. packer 6672 SWF

I.P. 2523 MCF/D After Hrs. SICP 1557 PSI After Days GOR Grav. 1st Del. 8-12-82

TOPS	NITD	X	Well Log	TEST DATA
Kirtland	C-103	✓✓✓✓	Plat	Schd. PC Q PW PD D Ref.No.
Fruitland	1425 C-104	✓3-26-81	Electric Log	XX 10/2/82 914 632 363 731 334
Pictured Cliffs	1900 11-10-82	OK 12/2	C-122	✓ 10/2/82 914 632 363 731 177
Cliff House	3700	Ditr	Dfa	10/17/83 474 25 402 237 28
Menefee	Datr	Dac		6/1/84 536 190 390 429 82
Point Lookout	PT Data Abandoned in Drilling 4-8-82 The approved DHC-369			
Manco	4800	81		
Gallup	5815	82		
Sanostee		83		
Greenhorn	6710	84		
Dakota	6920			
Morrison				
Entrada				

R-7277

Gallup McDermott Co. SJ s 9 T 32N R 12W U Oper. Amoco Production Co Lse. Stanolind Gas Com E No. 1

F

30-045-24149

12-20-79

F. Loc. 1390/S; 890/E Elev. 6071 GL Spd. 5-17-80 Comp. 1-15-81 TD 7109 PB 6830

Casing S. 9 5/8 @ 372 W 300 Sx. Int. @ W Sx. Pr. 7 @ 7105 W 2315 Sx. T. 2 1/8 @ 6773
Csg. Perf. 6722-6778 Prod. Stim. SWF

I.P. 368 MCF/D After Hrs. SICP 1870 PSI After 14 Days GOR Grav. 1st Del. 8-12-82

TOPS	NITD	X	Well Log	TEST DATA
Kirtland	C-103	✓✓✓✓	Plat	Schd. PC Q PW PD D Ref.No.
Fruitland	1425 C-104	6-24-82	Electric Log	✓ 10/2/82 914 632 363 731 157
Pictured Cliffs	1900 11-10-82	OK 12/2	C-122	✓ 10/17/83 474 25 402 237 24
Cliff House	3700	Ditr	Dfa	6/1/84 536 190 390 429 79
Menefee	Datr	Dac		12/13/85 375
Point Lookout	NIT PB from Data 1-24-81 PT Data abandoned in drilling The approved DHC-369			
Manco	4800	81		
Gallup	5815	82		
Sanostee		83		
Greenhorn	6710	84		
Dakota	6920			
Morrison				
Entrada				

Grhn Co. SJs 9 T 32N R 12W U Oper. Amoco Production Co Lse. Stanolind Gas Com E No. 1