

(SUBMIT IN TRIPLICATE)

Indian Agency Alcarvilla Apache

Dulce, New Mexico

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Tribal

Lease No. 198

X			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 3, 1958

N.M. Apache

Well No. 1 is located 790 ft. from S line and 990 ft. from W line of sec. 21

SW 1/4 Sec. 21

(1/4 Sec. and Sec. No.)

23N

(Twp.)

5W

(Range)

N 1/2 M

(Meridian)

Undesignated

(Field)

Sandoval

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the ~~drill-hole~~ above sea level is 6661.7 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 6:00 P.M., 11-28-58. Drilled 13 3/4" hole to 330'. Set 9 5/8" 32.3
H-40 STAG @ 324' w/275 ex most 2% CaCl. Circulate 50 ex to surface. Plug down
5:00 A.M., 11-29-58. WOC 24 hrs. Tested casing and BOP to 1000' for 30 min.
O.K.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sunray Mid-Continent Oil Company

Address Box 128

Hotchkiss, New Mexico

By [Signature]

Title Engineer