

DISTRIBUTION		
NTA FE		
LE		
S.G.S.		
AND OFFICE		
PERATOR.		

NEW MEXICO OIL CONSERVATION COMMISSION

Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 14-08-0001-12395	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Borehole
Name of Operator Gas Company of New Mexico		
Address of Operator 1st International Bldg., Suite 1800 Dallas, TX 75270		
Location of Well UNIT LETTER <u>N</u> <u>553</u> FEET FROM THE <u>South</u> LINE AND <u>1723</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>15N</u> RANGE <u>1E</u> NMPM.		

7. Unit Agreement Name Las Milpas
8. Farm or Lease Name San Ysidro
9. Well No. 50
10. Field and Pool, or Whichever Gas Storage
12. County Sandoval

15. Elevation (Show whether DF, RT, GK, etc.)
5827' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
ILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Moved in L & B Speed Drilling and drilled 4 3/4" hole to 230' using air as drilling medium. The hole was drilled to 230' and the samples were used to aid in Geological evaluation of the area, (spudded 6/27/79), (plugged 10/16/79).

The hole was cemented from TD to the surface.

The surface area has been cleaned up by the Gas Company of New Mexico.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ronald A. Chavez TITLE Drig & Production Engineer DATE July 20, 1981

PROVED BY Original Signed by FRANK T. CHAVEZ TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: